Location East Japan (Tochigi)





| Product Details    |                   |                       |                          |                  |
|--------------------|-------------------|-----------------------|--------------------------|------------------|
| Brand              | SCANIA            | Product Name          |                          |                  |
| Segment            | Large             | Body                  |                          | Wing(Alu/Canvas) |
| Model Year         | 2019              | Description           |                          |                  |
| Vehicle ID         | YS2R6X20005521*** | Payload               |                          | 13,400kg         |
| Gross Weight       | 24950             | Mileage               |                          | 684,000km        |
| Engine             | DC09              | Transmission          |                          | AT               |
| Horse Power        | 360               | Displacement          |                          | 9.29             |
| Fuel               | Light oil         | Passengers            |                          | 2                |
| Vehicle inspection | August 28, 2007   | Recycling Ticket      |                          | 14910            |
| Body Information   |                   |                       |                          |                  |
| Manufacturer       | Nippon Trex       | Cargo Size<br>(Inner) | L961cm x W241cm x H259cm |                  |
| Special Remarks    |                   |                       |                          |                  |

Snow-melting specifications, high roof, raised floor, 3-axle, aluminum wheel bed, ET2.0, rearview camera. Manufacturer: Nippon Trex. Gate frame (cm): W237 x H251. Floor: Wood. Lashing rails: 2-level. Floor clearance: 105cm. For used trucks, trust Truckland! We offer vehicle inspections and test drives. For financing and leasing options, please contact our sales representative.