


Location East Japan (Tochigi)





	Produ	ict Details		
Brand	SCANIA	Product Nar	ne	
Segment	Large	Body		Wing(Alu/Canvas)
Model Year	2019	Description		
Vehicle ID	YS2R6X20009349***	Payload		13,200kg
Gross Weight	24970	Mileage		1,000km
Engine	DC13-G2	Transmissio	n	Escot
Horse Power	420	Displaceme	nt	12.74
Fuel	Light oil	Passengers		2
Vehicle inspection	January 28, 2008	Recycling Ti	cket	14510
	Body I	nformatio	า	
Manufacturer	Trantex	Cargo Size (Inner)	Cargo Size (Inner) L956cm x W238cm x H259cm	
	Specia	al Remarks	5	

New Scania SUPER, medium-low floor, 3-axle, rear air suspension, high roof, bed, back-eye camera [Top item] Manufacturer: Trantex Gate frame (cm): W236 x H250 Floor: wood Lashing rail: 2-stage Floor height above ground: 105cm If you are looking for a used truck, leave it to Truckland! We are accepting inspections and test drives of the actual vehicle. Please consult with our staff regarding loans and leasing.